
HOME REPORT

FOR CLIENTS OF:



48
Jubilee Court
76 St. Margaret Street
Dunfermline
KY12 7PF





- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire

survey report on:

Property address	48 Jubilee Court, 76 St Margaret Street, Dunfermline, KY12 7PF
Customer	Mrs Marion Glen Lonie
Customer address	48 Jubilee Court, 76 St. Margaret Street, Dunfermline, KY12 7PF
Prepared by	DM Hall
Date of inspection	19th December 2024



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	Second floor flat within a part two, part three and part four storey purpose built block of retirement flats.
Accommodation	SECOND FLOOR: Hall, Living/Dining Room, Kitchenette, Bedroom with Dressing Area and Shower Room.
Gross internal floor area (m²)	53 square metres approx.
Neighbourhood and location	The property forms part of an established development of retirement flats on the south side of Dunfermline city centre. The location is convenient for all city centre amenities.
Age	Built around 2001.
Weather	Dry and bright.
Chimney stacks	None.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	ROOF: The roof is pitched and slated. There is metal ridging fixed with metal clips. There are various metal valleys where the roof slopes adjoin each other.
	ROOF SPACE: The roof space is accessed from a ceiling hatch in the hallway. The roof is timber framed and there is underslate felt.

Rainwater fittings Visually inspected with the aid of binoculars where appropriate. Gutters are of half round PVC design with round PVC downpipes. Wisually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building. Garages and permanent outbuildings None.		
Appropriate. Gutters are of half round PVC design with round PVC downpipes. Wisually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Roofing including roof space	ceiling joists.
Appropriate. Gutters are of half round PVC design with round PVC downpipes. Wisually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
Main walls Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. Ther is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Rainwater fittings	· · · · · · · · · · · · · · · · · · ·
appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		Gutters are of half round PVC design with round PVC downpipes.
appropriate. Foundations and concealed parts were not exposed or inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
inspected. The main walls are of 300mm cavity brick/concrete block, rendered externally with synthetic stone features. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Main walls	
Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		·
keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
Doors and windows were not forced open. WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. Visually inspected. External joinery is paint finished. Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Windows, external doors and joinery	·
WINDOWS: Windows are of double glazed timber framed variety. EXTERNAL DOORS: The entrance door into the flat from the common hall is of timber framed and panelled type. Visually inspected. External joinery is paint finished. Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		Random windows were opened and closed where possible.
External decorations Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		Doors and windows were not forced open.
Conservatories / porches Visually inspected. External joinery is paint finished. Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		WINDOWS: Windows are of double glazed timber framed variety.
External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
External joinery is paint finished. Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Communal areas Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
Conservatories / porches Visually inspected. There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	External decorations	Visually inspected.
There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		External joinery is paint finished.
There is an open entrance canopy to the front of the building built of brick/concrete block walls, rendered externally under a pitched and slated roof. Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Conservatories / porches	Visually inspected
Circulation areas visually inspected. The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Concertations per ente	
The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		of brick/concrete block walls, rendered externally under a pitched
The property has several communal areas including the entrance hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.		
hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the building.	Communal areas	Circulation areas visually inspected.
Garages and permanent outbuildings None.		hall and various hallways, residents lounge, refuse area and laundry. There is also a guest flat within the block and a manager's office. The property benefits from a lift connecting all floors in the
Garages and permanent outbuildings None.		
	Garages and permanent outbuildings	None.

Outside areas and boundaries	Visually inspected.
	The building is set within mutual grounds. There is an area of lawn, flower beds and shrubs to the south of the building. This is
	enclosed by stone walls and timber fencing. To the front (north) of
	the building there are common grounds including car parking area and access road.
Ceilings	Visually inspected from floor level.
	Ceilings are lined with plasterboard. There is some plasterboard coving and some textured plaster finishes.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls and partitions are lined with plasterboard.
	There is wet wall panelling in the shower room.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring is of solid concrete.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal joinery finishes are of timber.
	Interior doors are timber framed and panelled and the kitchenette door has glazed inserts.
	The kitchen consists of fitted floor and wall mounted units.
Chimney breasts and fireplaces	None.

Internal decorations	Visually inspected.
	Internal decorations comprise painted finishes.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply with the meters and consumer units in the hall cupboard.
	Visible wiring is run in PVC coated cabling with 13 amp power outlets.
Coo	
Gas	No gas supply.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	·
	appliances.
	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand
	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin.
	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials.
Heating and hot water	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials.
Heating and hot water	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart
Heating and hot water	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or
Heating and hot water	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. Heating is from Fisher electric radiators in the living room and
Heating and hot water Drainage	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. Heating is from Fisher electric radiators in the living room and bedroom.
	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. Heating is from Fisher electric radiators in the living room and bedroom. There is a Hyco electric hot water unit in the hall cupboard. Drainage covers etc were not lifted.
	appliances. Mains water supply. The shower room is furnished with a modern white suite comprising double shower cabinet with electric shower, wc and wash hand basin. All visible pipework is formed in copper and PVC materials. There is a stainless steel sink unit in the kitchen. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. Heating is from Fisher electric radiators in the living room and bedroom. There is a Hyco electric hot water unit in the hall cupboard.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

There are smoke detectors fitted. There is a pull cord emergency system. These were not checked.

Legislation by the Scottish Government, which took effect from February 2022, requires all residential properties to have a system of inter-linked smoke alarms and heat detectors. Carbon monoxide detectors are also required where appropriate. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection

For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property was fully furnished, occupied and all floors were covered. My visual inspection of the roof space area was restricted by stored items and also insulation material laid between the ceiling joists.

In accordance with Health and Safety guidelines I have not disturbed insulation, furniture or personal effects (particularly in cupboards). Floor coverings have not been moved.

Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.

Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.


Concealed areas beneath and around bath/shower trays were not visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.

The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.

Any additional limits to inspection	Where repairs are required at height compliance with Health and
	Safety legislation often requires the use of scaffolding which can
	significantly impact on the cost of repair. Pricing repairs is out with
	the remit of this report but it would be prudent to consider costs
	and budgeting before offering. The various trades can advise

further.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5) Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- (35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- (39) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No obvious evidence of significant movement noted within the limitations of my inspection.

Dampness, rot and infestation	
Repair category	1
Notes	No obvious evidence of significant dampness, rot or wood boring insect infestation.

Chimney stacks	
Repair category	-
Notes	None.

Roofing including roof space	
Repair category	1
Notes	There is some vegetation growth to the skews/copings.

Rainwater fittings	
Repair category	1
Notes	There are some weeds in the gutters.

Main walls	
Repair category	1
Notes	There is some shrinkage cracking to the rendering of the elevations.

Windows, external doors and joinery	
Repair category	1
Notes	External joinery will require ongoing maintenance.

External decorations	
Repair category	1
Notes	Regular repainting of external joinery will prolong its lifespan.

Conservatories/porches	
Repair category	1
Notes	No significant defects evident.

Communal areas	
Repair category	1
Notes	No significant defects evident.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries	
Repair category	1
Notes	No significant defects evident.

Ceilings	
Repair category	1
Notes	No significant defects evident.

Internal walls	
Repair category	1
Notes	No significant defects evident.

Floors including sub-floors	
Repair category	1
Notes	No significant defects evident.
	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant defects evident.

Chimney breasts and fireplaces	
Repair category	-
Notes	None.

Internal decorations				
Repair category	1			
Notes	No significant defects evident.			

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	1
Notes	It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	-
Notes	No gas supply.

Water, plumbing and bathroom fittings					
Repair category	1				
Notes	Sanitary fittings are to a modern standard with no significant defects evident.				

Heating and hot water					
Repair category	1				
Notes	It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations.				

Drainage	
Repair category	1
Notes	No significant defects evident.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	1
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	-
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Second		
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X		
3. Is there a lift to the main entrance door of the property?	Yes X No		
4. Are all door openings greater than 750mm?	Yes X No		
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No		
6. Is there a toilet on the same level as a bedroom?	Yes X No		
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No		
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No		

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The property was built by McCarthy & Stone, specialists in retirement housing. It is understood that management is carried out by Trinity Factors. The completing conveyancer should verify all costs in respect of factoring and the obligations within the development.

Estimated reinstatement cost for insurance purposes

£135,000 (ONE HUNDRED AND THIRTY FIVE THOUSAND POUNDS).

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

Valuation and market comments

£110,000 (ONE HUNDRED AND TEN THOUSAND POUNDS).

MARKET COMMENTS: Interest rates have now stabilised and there have been two small cuts in the Bank Base Rate in recent months. Hopefully this is having a positive effect on the market.

Signed	Security Print Code [533896 = 7206] Electronically signed					
Report author	Alasdair Seaton					
Company name	DM Hall					
Address	27 Canmore Street, Dunfermline, KY12 7NU					
Date of report	20th December 2024					



Property Address								
Address 48 Jubilee Court, 76 St Margaret Street, Dunfermline, KY12 7PF Seller's Name Mrs Marion Glen Lonie Date of Inspection 19th December 2024								
Property Details								
Property Type	House Bungalow Chalet Purpose built maisonette Coach Studio Converted maisonette X Purpose built flat Converted flat Flat over non-residential use Other (specify in General Remarks)							
Property Style	□ Detached □ Semi detached □ Mid terrace □ End terrace □ Back to back □ High rise block X Low rise block □ Other (specify in General Remarks)							
Does the surveyor be e.g. local authority, m	elieve that the property was built for the public sector, Yes X No nilitary, police?							
Flats/Maisonettes on	ly Floor(s) on which located Second No. of floors in block 4 Lift provided? X Yes No No. of units in block 47							
Approximate Year of	Construction 2001							
Tenure								
X Absolute Ownership	Leasehold Ground rent £ Unexpired years							
Accommodation								
Number of Rooms	1 Living room(s) 1 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks)							
Gross Floor Area (ex	cluding garages and outbuildings) 53 m² (Internal) 60 m² (External)							
Residential Element	(greater than 40%) X Yes No							
Garage / Parking /	Outbuildings							
Single garage Available on site?	□ Double garage ▼ Parking space □ No garage / garage space / parking space ▼ Yes □ No							
Permanent outbuildin	ngs:							
None.								

Construction									
Walls	X Brick	Stone		Concrete	Timb	er frame			
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Solid	X Cavity		Steel frame		rete block	Oth	er (specify in Ge	neral Remarks)
Roof	Tile	X Slate		sphalt	Felt			(-1)	,
	Lead	Zinc		· Artificial slate	Flat g	glass fibre	Oth	er (specify in Ge	neral Remarks)
Special Risks									
Has the property su	iffered structi	ural movem	ent?					Yes	X No
If Yes, is this recent	t or progressi	ve?						Yes	No
Is there evidence, h immediate vicinity?	istory, or rea	son to antic	ipate sub	sidence, h	neave, la	andslip (or flood in th	ne Yes	X No
If Yes to any of the	above, provi	de details in	General	Remarks.					
Ci C									
Service Connecti									
Based on visual ins of the supply in Ger			ces appe	ar to be no	on-main	s, pleas	e comment	on the type a	nd location
Drainage [X Mains	Private	None			Water	X Mains	Private	None
Electricity	X Mains	Private	None			Gas	Mains	Private	X None
Central Heating [Yes	Partial	X None						
Brief description of	Central Heat	ing:							
No central heating	g. Heating is	provided by	Fisher el	ectric radi	ators.				
Site									
Apparent legal issue	es to he verif	ied by the c	onvevano	er Please	nrovid	e a hrief	description	in General R	emarks
	X Shared drive	-		e or other an	-		_	ared service con	
Agricultural land inclu				ned boundari		i coparati		her (specify in Ge	
		,						(4)	,
Location									
Residential suburb	X Resi	dential within t	own / city	Mixed	residentia	I / comme	rcial Ma	ainly commercial	
Commuter village	Rem	ote village		Isolate	d rural pro	perty	Otl	her (specify in Ge	eneral Remarks)
Planning Issues									
Has the property be	en extended	/ converted	d / altered	? Ye	s X No				
If Yes provide detai	ls in General	Remarks.							
Roads									
Made up road	Unmade road	Partly	/ completed	new road	Pe	edestrian a	access only	X Adopted	Unadopted

CONDITION: The property is generally in a condition commensurate with age and type. Some items of routine maintenance will be required in due course. REMARKS: The property was built by McCarthy & Stone, specialists in retirement housing. It is understood that management is carried out by Trinity Factors. The completing conveyancer should verify all costs in respect of factoring and the obligations within the development.
Essential Repairs
No essential repairs noted. No essential repairs noted.

Comment on Mortgageability				
The property forms suitab of the mortgage provider.	le security for normal mortgage lending purposes subject to the specific le	ending criteria		
Valuations				
Market value in present condition £ 110,0 Market value on completion of essential repairs £ Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) Is a reinspection necessary? Yes X				
Buy To Let Cases				
month Short Assured Tenai	ge of monthly rental income for the property assuming a letting on a 6 ncy basis? There there is a steady demand for rented accommodation of this type?	£ Yes No		
Signed Surveyor's name Professional qualifications Company name Address	Security Print Code [533896 = 7206] Electronically signed by:- Alasdair Seaton BSc MRICS DM Hall 27 Canmore Street, Dunfermline, KY12 7NU			
Telephone Fax Report date	01383 621262 01383 621282 20th December 2024			

Energy Performance Certificate (EPC)

Dwellings

Scotland

48 JUBILEE COURT, 76 ST MARGARET STREET, DUNFERMLINE, KY12 7PF

Dwelling type: Top-floor flat
Date of assessment: 19 December 2024
Date of certificate: 19 December 2024

Total floor area: 53 m²

Primary Energy Indicator: 253 kWh/m²/year

Reference number: 9170-2881-4020-2194-8321 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst


Main heating and fuel: Room heaters, electric

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,336	See your recommendations
Over 3 years you could save*	£846	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (71)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (72)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 High heat retention storage heaters	£800 - £1,200	£849.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, insulated (assumed)	****	★★★★ ☆
Roof	Pitched, 200 mm loft insulation	****	★★★★ ☆
Floor	(another dwelling below)	_	_
Windows	Fully double glazed	***	★★★☆☆
Main heating	Room heaters, electric	****	***
Main heating controls	Programmer and room thermostat	****	★★★★ ☆
Secondary heating	None	_	_
Hot water	Electric instantaneous at point of use	****	***
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 43 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.3 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

Estimated energy costs for this nome				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£2,172 over 3 years	£1,326 over 3 years		
Hot water	£930 over 3 years	£930 over 3 years	You could	
Lighting	£234 over 3 years	£234 over 3 years	save £846	
	Totals £3,336	£2,490	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


December de disservation	lu diantius annt	Typical saving	Rating after improvement	
Recommended measures	Indicative cost	per year	Energy	Environment
High heat retention storage heaters	£800 - £1,200	£283	C 77	C 71

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 High heat retention storage heaters

Modern storage heaters are less expensive to run than the direct acting, on-peak heating system in the property. A dual-rate electricity supply is required to provide the off-peak electricity that these heaters use; this is easily obtained by contacting the energy supplier. Ask for a quotation for high heat retention with automatic charge and output controls. Installations should be in accordance with the national wiring standards. Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified electrical heating engineer. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	3,043	N/A	N/A	N/A
Water heating (kWh per year)	1,080			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Alasdair Seaton

Assessor membership number: EES/009394

Company name/trading name: D M Hall Chartered Surveyors LLP

Address: 27 Canmore Street

Fife

Dunfermline KY12 7NU

Phone number: 01383 604100

Email address: william.knight@dmhall.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



Property Questionnaire

Property address:	48 SUBILEE COURX TO SX MARGAREX SXREEX		
	DONKERMLINE		
	500		
	FIFE SCOXLADD		
	K412 784		
Seller(s):	MRS MARION LONIE		
Completion date of property questionnaire:	17.12.24		

PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

PROPERTY QUESTIONNAIRE Information to be given to prospective buyer(s)

1.	Length of ownership
	How long have you owned the property?
2.	Council Tax
7 24	Which Council Tax band is your property in? (Please circle)
	A B C D E F G H
3.	Parking
	What are the arrangements for parking at your property?
	(Please indicate all that apply)
	Garage
,	Allocated parking space
	• Driveway
	Shared parking
	On street
	Resident permit
	Metered parking
	Other (please specify):

4.	Conservation Area	HONY Implini
- 1	Is your property in a designated Conservation Area (that is an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes/No/ Don't know
5.	Listed Buildings	2. Gou
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No
6.	Alterations / additions / extensions	land e
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? If you have answered yes, please describe the changes which you have made:	Yes/No
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes/No

	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them.	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes/No
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes/No
	(ii) Did this work involve any changes to the window or door openings?	Yes/No
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	

7.	Central heating	ov ii neen
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).	Yes/No/ Partial
	If you have answered yes/partial – what kind of central heating is there?	
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)	
	FISCHER ELECTRIC RADIATORS IN LOUNGE AND BEDROOM + DIMPLEX WALL HEAKERS IN	
	BAXHROOM AND KICHEN. NO HERTING IN HALL If you have answered yes, please answer the three	
	questions below:	- N=7 -
	(i) When was your central heating system or partial central heating system installed?	
	FISCUER RADIAXORS 2017 BIMPLEX WALL HEAKERS APPROX 2001 (CONSTR	
	(ii) Do you have a maintenance contract for the central heating system?	Yes/No
	If you have answered yes, please give details of the company with which you have a maintenance agreement:	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	

8.	Energy Performance Certificate	018
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes/No
9.	Issues that may have affected your property	<u></u>
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes/No
Water State	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes/No
b.	Are you aware of the existence of asbestos in your property? If you have answered yes, please give details:	Yes/No
	ii you iiuvo unovoiou yoo, pieuco g	
10.	Services	

a. Please tick which services are connected to your property and give details of the supplier:

Services	Connected	Supplier
Gas or liquid petroleum gas		
Water mains or private water supply	V	SCORKISH WAKER
Electricity		SCOKKISH
Mains drainage		SCOKIBU
Telephone		SVY
Cable TV or satellite	V	SKY

	Broadband	
b.	Is there a septic tank system at your property?	Yes/No
1093	If you have answered yes, please answer the two questions below:	
7; [P8]	(i) Do you have appropriate consents for the discharge from your septic tank?	Yes/No/ Don't Know
	(ii) Do you have a maintenance contract for your septional tank?	Yes/No
_	If you have answered yes, please give details of the company with which you have a maintenance contract:	
11.	Responsibilities for shared or common Areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Yes/No/ Don't Know
	If you have answered yes, please give details:	
	LIVING IN REKIREMENT FLARS, ALL OF	
	THE OWNERS SHARE RESPONSIBILITY	
	FOR COMMON AREAS	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes/No/ Not applicable
	If you have answered yes, please give details:	
	picaco give actalis.	1
	A3 14 QUESKION 11 A	

		A
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes/No
	GENERAL REPAIRS 2 MAINTENANCE	
d.	Do you have the right to walk over any of your	Yes/No
	neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	
	If you have answered yes, please give details:	
e.	As far as you are aware, do any of your neighbours	Yes/No
C.	have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	
	If you have answered yes, please give details:	
f.	As far as you are aware, is there a Public Right of Way across any part of your property? (public right of way is a way over which the public has a right to pass,	Yes/No
	whether or not the land is privately-owned.)	
	If you have answered yes, please give details:	2 B
		= ²
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	Yes/No
	If you have answered yes, please provide the name and	
	address and give details of any deposit held and approximate charges: 1212149 FACCOLIDG BRUNCSFIELD PLACE EDIABURGH	

-3/40	APPROXIMANTE CHARGES E1400 Per annum	Hart -
b.	Is there a common buildings insurance policy?	Yes/No Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No Don't know
C.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	77.1
	en i de la company de la compa	
	See in the	
13.	Specialist Works	
13.	Specialist Works As far as you are every bee treatment of the state o	
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	Yes/No
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the	Yes/No
13. a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the	Yes/No

C.	If you have answered yes any guarantees relating to the sedent by the purchaser solicitor as soon as possion not have them yourself plantese documents and you arrange for them to be ob provide a description of the sedont shown in the original Guarantees are held by:	to 13 this thesand s ible for ease v r soli tained	(a) or work? hould or che- write l citor o	(b), do yo cantees w be given cking. If y below wh or estate a will also ried out.	rill be to your you do <u>o has</u> agent will o need to	Yes	/No
14.	Guarantees						
	A	OH 14/6	rront	ioc for an	v of the		
a.	Are there any guarantees following:	OI Wa	arranı	ico iui ali	y OI tile		
(i)	Electrical work	No	Yes	Don't	With tit	-	Lost
				Know	deeds		1 254
(ii)	Roofing	(No)	Yes	Don't Know	With tit		Lost
(iii)	Central heating	No	Yes	Don't	With ti		Lost
("")	Join at Housing	113		know	deeds		
(iv)	National House Building Council (NHBC)	No	Yes	Don't know	With ti	76.0	Lost
(v)	Damp course	No	Yes	Don't know	With ti		Lost

(vi)		h title eeds	Lost
b.	If you have answered 'yes' or 'with title deeds', pleasof the work or installations to which the guarantee(s	se give o	details s):
C.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:	Ye	es/No
15.	Boundaries	dectrica	(1)
> ₂ -	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:	D	s/No/ on't now

16.	Notices that affect your property	
	In the past three years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know
b.	that affects your property in some other way?	Yes/No/ Don't know
C.	that requires you to do any maintenance, repairs or improvements to your property?	Yes/No/ Don't know
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.	

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s)):		
	*	*	
	. A		

Date: 17.12.24

