9 Market Place, Downham Market PE38 9DG 01366 385588 info@kingpartners.co.uk





Southery

Downham Market, PE38 0PN



SALES • LETTINGS • MORTGAGES

(01366 385588 🌙

info@kingpartners.co.uk



£325,000







UPVC Double Glazed Door To:

Entrance Hall

 $13'\,4''\times5'\,5''$ (4.06m \times 1.65m) Max. Staircase to first floor. Telephone point. Doors to living room, kitchen/breakfast room and opening to dining room.

Living Room

13' 3" \times 12' 11" (4.04m \times 3.94m) UPVC double glazed bay window to front. UPVC double glazed window to side. Wood burning stove to feature fireplace. Two radiators. Television point.

Dining Room

13' 2" \times 10' 8" (4.01 m \times 3.25m) UPVC double glazed bay window to front. Radiator.

Conservatory

16' 5" \times 9' 7" (5.00m \times 2.92m) UPVC double glazed construction. Double doors to garden.

Kitchen/Breakfast Room

13' 6" \times 13' 3" ($4.1\,\mathrm{Im}\,\times$ $4.0\,\mathrm{4m}$) Fitted with a range of wall and base units with stainless steel sink and drainer with mixer taps. Space for electric oven and fridge. Cast iron wood burning stove within feature fireplace. Tiled floor. Sash window to side. Radiator. Half glazed door to conservatory. Door to rear lobby.

Rear Lobby

2' $9" \times 5'$ 0" (0.84m \times 1.52m) Tiled floor. Opening to utility room. Door to shower room.

Utility Room

8' 5" \times 7' 5" (2.57m \times 2.26m) Two UPVC double glazed windows. Fitted with wall and base units. Space for washing machine and tumble dryer. Oil fired boiler. Space for fridge freezer. Tiled floor. Radiator.

Shower Room

5' 3" \times 5' 1" (1.60m \times 1.55m) UPVC double glazed window. Tiled shower cubicle. Wash hand basin. W.C. Radiator. Fan heater.

First Floor Landing

UPVC double glazed window panel. Radiator.

Bedroom I

13' I" \times 12' 9" (3.99m \times 3.89m) UPVC double glazed window to front and side. Radiator.

Bedroom 2

13' 3" \times 13' 1" (4.04m \times 3.99m) Max. UPVC double glazed window to front and side. Radiator:

Bedroom 3

 $6'\,2"\times13'\,1"$ (1.88m \times 3.99m) UPVC double glazed window to side and rear. Built in double cupboard. Radiator.

Bathroom

7' I" \times 10' I" (2.16m \times 3.07m) Corner bath with mixer shower W.C. Wash hand basin.. Heated towel rail. Loft access.

Agents Note:

In 1996 the property was underpinned through an insurance claim. No further signs of subsidence have occurred since. There has been a new septic tank installed in the grounds of the property to meet the latest regulations. The photographs of the river bank have been taken using the current access via the additional garden area.

Disclaimer

Whilst we have endeavoured to prepare our sales particulars accurately none of the services, appliances or equipment have been tested. A buyer should satisfy themselves on such matters prior to purchase. Any measurements or distances mentioned in these particulars are for guide reference only. If such particulars are fundamental to a purchase, buyers should rely on their own enquiries. All enquiries should be directed to King & Partners in the first instance.